
West Manhood Drainage Improvement Group

This extract from the OS map is under licence to the Parish Council for monitoring land drainage and maintenance. It should not be reproduced. We welcome further detailed survey information from any source. © Crown Copyright. All rights reserved . Licence No. 100050851



West Manhood Drainage Improvement Group

The Ditch network between itchenor Cottage and Pond Cottage is very large for storing water but largely overgrown. The planted trees provide screening but have not been managed and the field access has become a tipping area for grass. This is common Land and a pumped foul rising main passes nearby.

I have suggested that the screening to farm buildings should remain but that a clear track is made for an excavator and maintained in front of the ditch at Langley, Itchenor Cottage, the Ponds and Lark rise.
Would the PC resolve to do this.